M. A. R. 57 (Rule 116) No. E

Measurement Book

483306

012-18-000019

Serial No. 1st & final

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency..... M/s KRIDL Technical Manager [West

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	NAME of WORK:- Repairs and Extension of UGD Line in Abbigere Village Surrounding area in W.No.12, Shettyhalli sub division.						
	Job code : 012-18-0000 19						
	W.O. NO. : EE/DD/WO/399/2019-20 dt: 21-09-2019.						
	A.S. NO. : EE/DD/AS/47/18-2019. dt- 29-01-2019						
	T.S. NO : EE/DD/TS/56/19-20 -dt 23-09-2019.						
	Estimated Cost : Rs. 50.00 Lakhs.						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿ...

ಪೀಣ್ಯ ಉಪವಿಭಾಗ, ದಾಸರಹ...

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗ...

2. Certified that the ...

3. Certified that the ...

Engineer

EXECUTIVE ...

Pasawanahalli Mahanagar ...

Bengaluru-56.

MEASUREMENT BOOK

Full description, etc. of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
Description of Item	unit	Qty		Rate		Amount
Earthwork Excavation	cum	6083.75		189.74		1155469.17
300mm Stoneware Pipe	Mt	3206.40		568.16		1821748.22
C.C. M7.5	Mt	530.00		518.34		274720.20
Circular type manhole	Nos	10.00		25741.04		257410.40
Dump available earth	cum	6089.75		128.26		781071.34
				TOTAL		4290419.32
				I/R SDL charges 4.5%		193068.87
				GST charges 12%		514850.82
				GRAND TOTAL	=	Rs. 4998338.51

4976886

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಯಲಹಂಕ ನಗರ, ಬೆಂಗಳೂರು

Audited and admitted for Rs. 4976886/- 4998338=00
Passed by C... Rs. 4471298/- 4492450=00
Four Four lakh Ninety two thousand four hundred fifty only
Serial No. ...
Name of work ... From ... To ...
Name of Contractor of nature of Agency ...
Date of sponsor/commencement of work ...

Accounts Superintendent
Date ...

E.E. ENGINEER

M. A. R. 57 (Rule 116)
Measurement Book

No. E 483307

Full description, etc. of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
1 2	3	4	5	6	7	8

Certificate : ① The contractor has work done satisfactorily

② The contractor has removed the debries from work site

③ There is no any departmental issued to Contractor.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
EXECUTIVE ENGINEER
KRIDL, BBMP DIVISON
BENGALURU-560 010

Rs. ...

... that the above has ...
... contractor has delay...
... has been execute...

1	Name of the Work
	...mate No. and date
	...chargeable

P0190 (Jo...
EE/DD/WO/399/19-20 da...
...chnical Manager(West). K...

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

"SKETCH"

Abbigere

1st cross
2nd cross
3rd cross
4th cross
5th cross
6th cross.

Chikkabanavara Main Road

Shivanjinappa Layout

Pattalappa Layout 2nd cross
1st cross

Thammaiah Garden

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ

M. A. R. 57 (Rule 116)
Measurement Book

No. E 483308

Serial No. .....
Name of work ..... From ..... To .....
Name of Contractor of nature of Agency.....
Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

"SKETCH"

8th cross

Main Road

Railway parallel Road

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Rs. ...
...above has ...
...has delay... executi...